

DL SOP FOR DL TOOL VERSION 1.2

Set up the DL cable and downloader

Ainge Hsu

Date:

Doc Ref: ASM/GEN-UG-014

Version: 0.01

Internal Validation

Name	Title	Date	Signature

Distribution List

Name	Title	Signature

Revision History

Version	Status	Change Summary	Date	Author
0.01	<u>P</u>	Created	2004/11/20	Ainge

P: Preliminary Phase

V: Review Phase

R: Release Phase

U: Update

File Name: Genug014.doc


1. Purpose

The purpose of this document is to describe that how to setup the ASM's DL cable and how to use the DL tool of version 1.4 for customer

2. Scope

This document is for ASM's customers' reference only.

3. Setup the Serial Download cable



1. Please remember the COM number in this setting. You need this value to set your DL tool.


4. Setting DL tool

1. Copy the download to your directory, there should be some file.


- AsmDigiSignEngine.dll
- ASMDwnld_XXXX.exe, the XXXX is the customer's name.
- ASMDwnld_XXXX.sig, the XXXX is the customer's name.
- MFC71.dll
- msvcp71.dll
- msucr71.dll

2. Please execute the exe file to run the DL tool.


The UI will be shown up.



3. Please select the Tools-> Configuration



you will get this UI.



Change the COM to the number of your Serial cable in your system. Please note that you should insert the serial cable in to your computer before you execute the DL program and the COM number will be shown up in the configuration page.


Please check these setting are the same the picture

Please check if you select all item

Please set the three check box in this stage while you download the SW because we still fine tune the memory allocation of our core SW and your should erase all the memory every time you downloading.

4. Close the configuration page.

5. Press the button to select the mot file that ASMobile provides.



6. Pressing Start and the Stop will be shown up and the start the button will be gray. Inter the COM cable into the USB2COM cable and insert the ME to the COM cable. Press the power key and the progress bar will start running.
7. After the Download complete is shown-up, the download process are complete.