

Nokia APAC NOL

1 (3)

SEAP TECHNICAL SUPPORT
ting

CONFIDENTIAL

Create Date
3 Oct 2008

ASB<RM-430>001

SERVICE TOOLS FOR RM-430 (1508i)

Introduction

This Technical Bulletin lists all Service Tools made and potentially needed for service of RM-430.

Nokia 1508i Modules / Variants

Technology	1900 MHz / CDMA IS-95 & IS-2000 1xRTT	
Model / Type Designator	1508i / RM-430	
GPS Technology Support	No	

Revision History:

Revision No.	Data Issued	Change Description
TB001	3-Oct-08	Initial release

Nokia APAC NOL

2 (3)

SEAP TECHNICAL SUPPORT
ting



CONFIDENTIAL

Create Date
3 Oct 2008

ASB<RM-430>001

NEW SERVICE DEVICES

List the new service devices used only for this product and the accompanying spare parts.

PRODUCT	Type	Code	Service Level	Comment/Picture
Module Jig, MJ-200	MJ-200	0780998	3	
Spare test Pin for Module jig, MJ-200		0781034	3	1 pcs = 10 pins
Domesheet Jig	SS-180	0780999	1,2,3	
AMS Software Protection Key (USB), PK-86	PK-86	0781000	3	

Nokia APAC NOL

3 (3)

SEAP TECHNICAL SUPPORT
ting

CONFIDENTIAL

Create Date
3 Oct 2008

ASB<RM-430>001

GENERIC AND REUSED SERVICE DEVICES USED WITH OTHER PHONES

PRODUCT	Type	Code	Service Level	Comment/Picture
Data Service Cable	CA-101	0730634	1,2,3	
Soldering Jig	RJ-230	0780264	2,3	
RF Service Cable	CA-128RS(10cm)	0730344	3	

-- END OF DOCUMENT --